

U.S. Department of Transportation

National Highway Traffic Safety Administration

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***



UMTRI - 96 - 8 VERSION 05

> **UM-3710-98 1998 GMC Suburban**

In-depth Vehicle Occupant Report

The University
of Michigan
Transportation
Research Institute

UMIVOR



UM-3710-98

Case Vehicle (A): 1998 GMC

Type: Suburban SLE, 4-door 4 x 4 APV

Driver: 18-year-old male

CDC: Ø1-FZEW-2, Ø3-RBEN-1

Veh. (B): 1993 Buick

Type: Regal Custom, 4-door sedan

Driver: 61-year-old female

CDC: Ø9-LPEW-3, Ø9-LBEE-1

Situation

(Slide 1) Case vehicle (A) was traveling north up a hill at an unknown speed, (slide 2) on a two-lane asphalt road in a rural residential/agricultural area. It was daylight, the sky was clear, and the road surface was dry and in good condition. (Slide 3) Vehicle (B) was stopped at the crest of a hill, at a "stop sign" facing west, on a two-lane gravel road. As case vehicle (A) approached the intersection at the crest of the hill, the driver did not see the stop sign and failed to stop. Case vehicle (A) struck vehicle (B) in the left-front fender with its right-front. Vehicle (B) rotated clockwise and then the right-rear quarter panel of case vehicle (A) struck the left-rear corner of vehicle (B), in a slap-together motion. (Slide 4) Case vehicle (A) came to rest facing north, just off the west edge of the road surface. Vehicle (B) came to rest facing north in the northbound lane.

(Slide 5) Damage to vehicle (B) was moderate. The maximum crush was 19 cm to the left-front fender just in front of the left wheel.

Using the WinSMASH accident-reconstruction program and (slides 6, 7 and 8) c-values measured for case vehicle (A) and (slides 9, 10 and 11) vehicle (B), the following crash severities were calculated for the frontal impact:

		Calculated Velocity Change - kph (mph)			
Vehicle	Variable	Total	Longitudinal	Latitudinal	
Case Vehicle (A)	EBS	31 (19)	-30 (-19)	-5 (-3)	
	Delta V	20 (12)	-20 (-12)	-3 (-2)	
Vehicle (B)	EBS	19 (12)	-3 (-2)	19 (12)	
	Delta V	29 (18)	-5 (-3)	29 (18)	

Exterior Damage

(Slide 12) Damage to case vehicle (A) was moderate. (Slide 13) The maximum crush was 31 cm to the right-center of the front bumper. (Slide 14) Using the undamaged portion of the front bumper (74 cm) and an undeformed end width (UEW) of 180 cm, the front-end overlap was calculated to be 59 percent. The vehicle overlap was calculated to be 58 percent using the overall width of 195 cm.

In the front, (slide 15) the grille, right headlight assembly, hood, and hood latch were damaged, the hood latch was jammed closed (pried opened by the body shop), and the rear edge of the hood was elevated, but it did not contact the undamaged windshield. (Slides 16 and 17) The engine compartment was damaged. On the right side, (slide 18) the front fender was damaged, and the front tire was flat, (slide 19) but there was no significant change in the wheelbase. On the left side, (slide 20) the front fender was damaged, but there was no significant change in the wheelbase. (Slide 21) There was no damage to the rear of the vehicle.

(Slide 22) The maximum right-side crush from the slap-together impact was 4 cm to the right-rear quarter panel.

Interior Damage

(Slide 23) This vehicle was equipped with steering-wheel and (slide 24) passenger frontal-impact airbags, which deployed. (Slides 25, 26 and 27) There was no damage to the steering-wheel rim or spokes, and no apparent rotation of the steering column. (Slides 28, 29, 30, 31, 32 and 33) There was no apparent damage to the interior.

Occupant Injuries and Kinematics

(Slide 34) The 5-ft, 11-in, 18-year-old male driver was wearing the three-point belt and (slide 35) the frontal-impact airbag deployed. A webbing imprint on the plastic D-ring is evidence of belt use during the crash. (Slide 36) The male driver of case vehicle (A) did not sustain any injuries, as noted in the attached table.

Occupant: Driver Restraints: 3-point belt worn and airbag deployed

Age: 18 years Stature: 180 cm (5 ft 11 in)

Sex: Male Mass: 95 kg (210 lb)

			Injury Source	
Injury Description	A.I.S.	Definite	Probable	Possible
No injury				
			,	
			1	
Maximum A.I.S. Level	<u>o</u>			
	ļ			
Injury Severity Score	0			

NO. OF CASE VEHICLES IN ACCIDENT

NUMBER OF SLIDES

15

16

ADMINISTRATIVE

AD-1

TEAM REPORT NUMBER

$$\frac{V}{16} M - 3 7 1 0 - 9 8$$

$$\frac{2}{20} - - - - - - - \frac{3}{27}$$

SPECIAL STUDY

(00) None

(01) Offset Frontal

(98) Not Applicable

9 9

DATE OF FIELD INVESTIGATION

, 48

INVESTIGATOR:

LOCATION WHERE VEHICLE WAS EVALUATED:



CIRCLE PHOTO RECORDS MADE:



NEGATIVES

POLAROIDS

REPORT PREPARED BY:




Duplicate columns 1-8 Module G 1 Format from the previous card.	0 1	GENERAL INFORMATION	GI-1
Time		ENVIRONMENTAL CONDITIONS	
	98	CONSTRUCTION ZONE	
DATE OF COLLISION m m d d	$\frac{1}{y} \frac{\delta}{y}$	(0) NO (1) YES (9) UNKNOWN	0
HOUR OF COLLISION D 8 4 (24 HOUR CLOCK)	<u>8</u> 22	ROAD ALIGNMENT VERTICAL PLANE	J,
LOCATION		(1) LEVEL (2) CREST OF HILL	2
STATE: Michigan		(2) SLOPE (2%) (3) SLOPE (2%) (4) BOTTOM OF HILL (9) UNKNOWN	2
STATE FIPS CODE	2 Ce	ROAD ALIGNMENT HORIZONTAL PLANE	
AREA		(1) STRAIGHT	t
(1) URBAN	10	(2) CURVE (3) T - SHAPED	23
(2) RURAL (9) UNKNOWN	2 25	(4) Y - SHAPED (7) OTHER:	
ENVIRONMENTAL CONDITIONS		SURFACE COVERING	
LIMITED-ACCESS HIGHWAY		(10) DRY	1
(0) NO (1) YES	<u>D</u>	(21) WATER - DAMP	34
(9) UNKNOWN	26	(22) WATER - WET (23) WATER - PUDDLED (29) WATER - AMOUNT UNKNOWN	
ROAD, TOTAL TRAFFIC LANES (FOR CASE VEHICLE)		(31) SNOW - LOOSE	
(1) 1-LANE		(32) SNOW - PACKED (39) SNOW - CONDITION UNKNOWN	
(2) 2-LANES (3) 3-LANES	2	(41) ICE	
(4) 4 OR MORE LANES	27	(51) SLUSH (61) SPILLED GRAVEL	
(5) DIVIDED, 4 OR MORE LANES (6) PARKING LOT/DRIVEWAY		(71) OTHER:	
(7) OTHER:(9) UNKNOWN		(99) UNKNOWN	
.,		VISIBILITY LIMITATION (FOR CASE VEHICLE)	
INTERSECTING RD, TOTAL LANES CHOOSE FROM ABOVE LIST, OR		(0) NONE	
(8) NOT APPLICABLE .	Z	(1) CLOUDY/DARK (2) FOG	38
(0)	28	(3) SMOKE (4) WINDSHIELD CONDITION	
		(5) GLARE	
TYPE OF ROAD SURFACE		(6) RAIN .(7) OTHER:	
(1) ASPHALT (2) CONCRETE	1	(B) ICE/SNOW (9) UNKNOWN	
(3) GRAVEL	29	VISIBILITY OBSTRUCTION	
(4) MORE THAN ONE (CIRCLE EACH) (7) OTHER:		(FOR CASE VEHICLE)	
(9) UNKNOWN		(0) NONE	D
ROAD DEFECTS		(1) BUILDING (2) SIGN	37
		(3) VEGETATION (E.G. BUSHES, SHRUBS) (4) TREE	
(0) NO (1) YES	$\frac{\mathcal{D}}{30}$	(5) HILL OR CURVE IN ROAD (6) VEHICLE IN TRANSPORT	
(9) UNKNOWN	3.	(7) OTHER:	
	1	(8) PARKED VEHICLE	1

		GENERAL INFORMATION GI-2
ENVIRONMENTAL CONDITIONS SPEED LIMIT (0) 5-45 km/h 5-25 mph (1) 46-55 30 (2) 56-60 35 (3) 61-70 40 (4) 71-79 45 / (5) 80-85 50 (6) 86-90 55 (7) 91-105 60 (8) OVER 105 65 (9) UNKNOWN	36	MECHANICAL MALFUNCTION WAS THERE MENTION OF A MECHANICAL MALFUNCTION IN CASE VEHICLE (0) NO (1) YES (2) YES, DID NOT CONTRIBUTE TO ACCIDENT (9) UNKNOWN
PRECIPITATION (0) NONE (1) RAIN (2) SNOW (3) HAIL (4) FREEZING RAIN/SLEET (7) OTHER: (9) UNKNOWN RATE OF PRECIPITATION (1) LIGHT/MIST (2) MODERATE (3) HEAVY (8) NOT APPLICABLE (9) UNKNOWN TEMPERATURE (0) BELOW -15° C BELOW 5° F (1) -15 TO -6 5 TO 22 (2) -5 TO -1 23 TO 31 (3) 0 TO 2 32 TO 36 (4) 3 TO 5 37 TO 41 (5) 6 TO 15 42 TO 59 (6) 16 TO 25 60 TO 77 (7) 26 TO 35 78 TO 95 (8) OVER 35 OVER 96	<u>O</u> 39 40 41	THE FOLLOWING SECTION SHOULD BE FILLED OUT IF A MECHANICAL MALFUNCTION IS RECOGNIZED OR SUSPECTED. CIRCLE ITEMS INVOLVED. SUPPORT ANY ITEMS CIRCLED WITH COMMENTS. BRAKE SYSTEM DRIVER CONTROLS EXHAUST SYSTEM POWER TRAIN STEERING SYSTEM FUEL SYSTEM SUSPENSION SYSTEM VISIBILITY ITEMS ELECTRICAL SYSTEM TIRES THROTTLE CONTROLS UNKNOWN OTHER: COMMENTS:
(9) UNKNOWN CROSSWIND (0) NONE (1) LIGHT (2) STRONG (3) GUSTY & STRONG (9) UNKNOWN LIGHT CONDITIONS (1) DAYLIGHT (2) DAWN (3) DUSK (4) DARK, LIGHTED (5) DARK, UNLIGHTED (6) DARK, UNKNOWN IF LIGHTED (9) UNKNOWN	42	

		GENERAL INFORMATION	GI-3
CRASH DETAILS CASE VEHICLE AND OBJECT (0) NO (1) YES	0	HIGHEST POLICE INJURY SEVERITY CODE IN CRASH (NOT JUST CASE VEHICLE) (0) O - NO INJURY (1) C - POSSIBLE INJURY	
(9) UNKNOWN CASE VEHICLE ROLLOVER (0) NO ROLLOVER (1) YES, FIRST EVENT (2) YES, SUBSEQUENT EVENT (3) YES, SEQUENCE UNKNOWN (9) UNKNOWN	<u>O</u> 46	(2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN	3 3
CASE VEHICLE RAN OFF ROADWAY (BEFORE FIRST IMPACT) (0) NO (1) YES (9) UNKNOWN	0	DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE) (0) NONE (1) YES (9) UNKNOWNNOT REPORTED/ NO DRIVER	<u>O</u>
MOVING CASE VEHICLE AND CONTACTED MOVING VEHICLE (0) NO (1) YES (9) UNKNOWN	1 48	DRIVER ALCOHOL BAC (CASE VEHICLE) (80) NO TEST (90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN	8 <u>0</u> 55 56
CASE VEHICLE AND CONTACTED STOPPED VEHICLE (0) NO (1) YES (9) UNKNOWN	<u>O</u>	WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	<u>O</u> 57
STOPPED CASE VEHICLE AND CONTACTED VEHICLE (0) NO (1) YES (9) UNKNOWN		LIST IMPAIRMENTS MENTION	NED:
TOTAL NUMBER OF VEHICLES CONTACTED BY CASE VEHICLE IN CRASH (8) 8 OR MORE (9) UNKNOWN		Post - Crash Detail MANNER CASE VEHICLE LEFT SCENE	
ANY FIRE IN THIS CRASH (NOT JUST CASE VEHICLE) (0) NO (1) YES (9) UNKNOWN	<u>O</u> 52	(1) DRIVEN (2) TOWED DUE TO DAMAGE (3) TOWED, NOT DUE TO DAMAGE (4) TOWED, REASON UNKNOWN (9) UNKNOWN	2 50

ACCIDENT DESCRIPTION: Case vehicle (A) was traveling weath	CASE VEHICLE (A): 1998 GMC Subunban	G
ACCIDENT DESCRIPTION: Case vehicle (A) was traveling worth And failed to stop at a "stop sign", striking	OTHER VEHICLE (B): 1993 Buick Regal	4
Vehicle (B) in the front-left with its right-front	THIRD VEHICLE (C):	
	——————————————————————————————————————	
	NORTH	



Duplicate columns 1-8 Module O V Format (from the previous card. 9 10 1	1 12	OTHER VEHICLE	OV-1
MAKE: Buick		CARGO:	
MODEL: Regal Custom, 4-de	oon sedan		
VIN 13		29	
MANUFAC/BODY CODE 2 1 2	2 <u>8</u> VEH	ICLE TYPE	
MAKE/MODEL CODE <u>0</u> 4 3	5 2 (0	SENGER VEHICLE 12) LARGE 13) LIMOUSINE 17) PICKUP CAR 18) LIMOUSINE RESERVE PROFIT OF THE PROPERTY OF THE PROFIT O	2 8 55
MODEL YEAR 1 9 <u>9</u>	3	20) UNKNOWN PASSENGER VEHICLE BODY 24) SUB-MINI 25) MINI 26) SUB-COMPACT	
VEHICLE MASS (kg) 0 0 1 5 1	I i.	7) COMPACT 8) INTERMEDIATE 9) FULL	
IF SEPARATE REPORT WAS MADE, GIVE VEHICLE NUMBER	<u>U</u> (1	TIPURPOSE PASSENGER VEHICLE 4) SMALL UTILITY (WHEELBASE LESS THAN 107', E.G. JEEP, BRONCO) 5) LARGE UTILITY (WHEELBASE MORE THAN 107', E.G. PANEL TRUCK SUBURBAN)	
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	49 (2 (2 (2 (2	6) PICKUP TRUCK WITH CANOPY/SHELL COVER 7) PICKUP CAR WITH CANOPY/SHELL COVER 11) MOTOR HOME 2) PICKUP TRUCK WITH SLIDE-IN CAMPER 3) PICKUP CAR WITH SLIDE-IN CAMPER 11) CHASSIS-MOUNTED CAMPER	
TRAVELING SPEED (km/h) 9 9	_		
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	(1 (1 (1 (1 (2 (3 (3	CK 1) VAN 2) PICKUP TRUCK 3) UNKNOWN LIGHT TRUCK 5) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) 6) PICKUP TRUCK WITH CANOPY/SHELL COVER 2) PICKUP TRUCK WITH SLIDE-IN CAMPER 0) UNKNOWN TRUCK TYPE 1) CHASSIS-MOUNTED CAMPER 3) DELIVERY VAN (WALK-IN)	
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE	(3)	4) STRAIGHT TRUCK 5) TRUCK-TRACTOR (BOBTAIL) 6) CHASSIS-CAB 7) UNKNOWN HEAVY TRUCK 8) TRACTOR & SEMI-TRAILER (SEMI)	-
(0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE (NOT APPLICABLE) (9) UNKNOWN	BUS (4 (4 (4 (4 (4 (6 (6	9) TRUCK (OR SEMI) & FULL TRAILER(S) 0) UNKNOWN BUS TYPE 1) SCHOOL BUS 2) INTERCITY BUS (BETWEEN CITIES) 3) TRANSIT BUS (INTRACTY) 4) STREETCAR (ON TRACKS) 8) TRAIN (CARS) 9) LOCOMOTIVE (ENGINE, SWITCHER) 9) UNKNOWN	
		ELBASE (cm) 99) UNKNOWN	273 56 57 58

Duplicate columns 1-8 from the previous card. Module 0 V Format 0 2 9 10 11 12

OTHER VEHICLE

OV-2

ORIGINAL SPECIFICATIONS

27	3_	cm
	27	273

Front Overhang

 $\frac{1}{22}$ $\frac{1}{24}$ cm

Curb Weight

Rear Overhang $\frac{1}{25} \frac{1}{6} \frac{1}{27} \text{ cm}$ Undeformed End Width (UEW) $\frac{1}{28} \frac{6}{30} \frac{2}{30} \text{ cm}$

Overall Length


$$\frac{4}{16}$$
 $\frac{9}{18}$ cm

Engine Displacement

Overall Width (OAW) $\frac{1}{19} \frac{8}{9} \frac{4}{31}$ cm

Engine: # of Cylinders

VEHICLE DAMAGE



FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL) $\frac{9}{35} = \frac{9}{37} = \frac{9}{37}$ cm

Front-End Overlap (Percent) = DDL UEW

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW) **OAW**


99%

Duplicate columns 1-8 from the previous card. Module V D Format 0 1 1 12	VEHICLE DESCRIPTION	VD-1
MAKE: GMC MODEL: SUBURBAN SLE, 4x4 SU	CARGO:	
VIN		29
MANUFAC/BODY CODE $\frac{1}{30} \frac{16}{15} \frac{1}{34}$	STOLEN VEHICLE	
MAKE/MODEL CODE 3 0 0 3	(0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	<u>8</u> 60 .
MODEL YEAR 1 9 <u>9</u> <u>%</u>		
VEHICLE MASS (kg) 0 0 2 5 1 8	BODY STRUCTURE	1
ODOMETER (km) (ENTER 9'S IF UNKNOWN) (ENTER 8'S IF ELECTRONIC) NUMBER OF OCCUPANTS 14, 488 willes 2 3 3 1 6 52	(1) BODY & FRAME (2) UNITIZED (3) INTEGRAL-STUB FRAME (4) BODY & PLATFORM FRAME (E.G. VW BUG)	61
(ENTER 9'S IF UNKNOWN) 54	(5) PARTIALLY UNITIZED (7) OTHER: (9) UNKNOWN	
TRAVELING SPEED (km/h) 4 9 57	TRANSMISSION	
(995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	(0) NONE (1) AUTOMATIC (2) MANUAL (9) UNKNOWN	62
VEHICLE TYPE		
PASSENGER VEHICLE (11) 2-DOOR HARDTOP (NO UPPER B-PILLAR) (12) 2-DOOR SEDAN OR COUPE (ANY UPPER B-PILLAR) (13) 4-DOOR HARDTOP (14) 4-DOOR SEDAN (15) STATION WAGON (16) CONVERTIBLE (18) OTHER PASS. VEH.: (19) PASSENGER VEHICLE, TYPE UNKNOWN	LOCATION OF TRANSMISSION SELECTOR LEVER (1) FLOOR (2) CONSOLE (3) COLUMN (7) OTHER: (9) UNKNOWN	3 8
MULTIPURPOSE PASSENGER VEHICLE (21) SMALL UTILITY (E.G. JEEP, SCOUT, BRONCO) (22) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (23) VAN, SIZE UNKNOWN (24) VAN, SMALL (MINI) (25) VAN, LARGE (29) MPV, TYPE UNKNOWN (30) MOTOR HOME	STEERING (1) POWER (2) MANUAL (9) UNKNOWN	
TRUCK (31) PICKUP TRUCK, UNKNOWN (32) PICKUP TRUCK, SMALL (DOWNSIZED) (33) PICKUP TRUCK, LARGE (99) UNKNOWN	BRAKES (1) POWER (2) MANUAL (9) UNKNOWN	65

		VEHICLE DESCRIPTION VD-2
TYPE OF BRAKES (1) DRUM, ALL WHEELS (2) DISC, FRONT WHEELS (3) DISC, ALL WHEELS (9) UNKNOWN	<u>Z</u>	WHEELBASE (cm) 3 3 74 75
BRAKE ANTI-LOCK DEVICE (0) NONE INSTALLED (1) TWO-WHEEL (2) FOUR-WHEEL (7) EQUIPPED, UNKNOWN WHEELS (9) UNKNOWN AIR CONDITIONING IN VEHICLE (0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	2 67 8 68	PLASTIC ANTI-LACERATIVE INNER LAYER GLASS EQUIPPED (0) NONE (1) WINDSHIELD (2) WINDSHIELD AND SIDE (7) OTHER (9) UNKNOWN
TYPE OF DRIVE (1) REAR WHEEL (2) FRONT WHEEL (3) FOUR WHEEL (4) ALL WHEEL DRIVE (9) UNKNOWN DUAL REAR WHEELS	1 69	FIELD INVESTIGATOR INSTRUCTIONS: 1. INDICATE CRUSHED AREAS BY <u>OUT-LINING NEW PERIMETER</u> OF VEHICLE AND SHADING THE DAMAGED AREAS ON THE LARGE SKETCH ON PAGE VD-3. USE AS MANY SKETCHES AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE.
(0) NO (1) YES (9) UNKNOWN	70	2. ENTER THE DIMENSIONS ON THE SKETCH(ES) MEASURED TO THE POINT OF MAXIMUM PENETRATION BY THE OBJECT(S) CONTACTED. USE THE
ORIGINAL TYPE OF RESTRAINT SYSTEM (1) ACTIVE BELT (2) PASSIVE BELT (3) AIRBAG (4) KNEE BOLSTERS (7) OTHER: (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	3 71	EXAMPLES BELOW AS A GUIDE. 3. ENTER THE THREE DIMENSIONS TO THE CENTER OF THE WHEELS (WHEELBASE, FRONT AND REAR OVERHANGS) ON BOTH SIDES OF THE CAR. 4. ADD OTHER DIMENSIONS AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. EXAMPLES:
EQUIPPED WITH ROLL BAR (0) NO (1) YES (9) UNKNOWN TYPE OF ROOF	<u>D</u>	FRONT OR REAR
(0) NONE (1) SOLID (2) T-TOP CLOSED (3) T-TOP OPEN (4) SUN ROOF CLOSED (5) SUN ROOF OPEN (6) CONVERTIBLE CLOSED (7) CONVERTIBLE OPEN (8) OTHER: (9) UNKNOWN	73	ROOF (REFERENCE TO TOP OF DOOR SALL OR WINDOW SILL)

Duplicate columns 1-8 from the previous card.	Module V D Format 0 2 9 10 11 12	VEHICLE DE	SCRIPTION VD-3
	ORIGINAL S	SPECIFICATIONS	
Wheelbase	334 cm	Front Overhang	0 9 2 cm
Curb Weight	2403 kg	Rear Overhang	$\frac{1}{25} \frac{3}{3} \frac{4}{27}$ cm
Average Track Width	13 6 1 cm	Undeformed End Width (UEW)	$\frac{1}{28}$ $\frac{g}{g}$ $\frac{g}{g}$ cm
Overall Length	5 5 8 cm	Engine Displacement	<u>5</u> . <u>7</u>
Overall Width (OAW)	$\frac{1}{19} \frac{9}{5} cm$	Engine: # of Cylinders	<u>O</u> <u>Y</u>

VEHICLE DAMAGE



FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A.

Front-End Overlap (Percent) = DDL

Direct Damage Length (DDL)

USEO UNDAMAGEN

LENG TH (14cm)

5 9 %

38 39 % Vehicle Overlap (Percent) = <u>DDL + 1/2 (OAW - UEW)</u> OAW

Duplicate columns 1-8 Module D A Form the previous card.	ormat <u>0</u> <u>2</u>	DAMAGE DA-1
PRIMARY	CASE VEHICLE PRIMARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER	13	
IMPACT SPEED (km/h)	9 9 9	$\frac{9}{35} \frac{9}{36} \frac{9}{37}$
ESTIMATED BY	17	
CRUSH (cm)	O 3 1 18 19 20	<u>O</u> <u>J</u> <u>9</u>
CDC #1	<u>0</u> 1. F2 EW. 2	09.6FEW.3
CDC #2	98.0000.0	98.0000.0
Duplicate columns 1-8 Module D A Form the previous card. 9 10	ormat <u>0 3</u>	
SECONDARY	CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER	<u>2</u>	
IMPACT SPEED (km/h)	999	$\frac{q}{3}\frac{q}{3}\frac{q}{3}$
ESTIMATED BY	1	1
CRUSH (cm)	<u>O</u> <u>O</u> <u>Y</u> 18 19 20	O O 3 39 40 41
CDC #1	<u>0</u> 3. R B E N. 1	09.LBEE.1
CDC #2	98.0000.0	98.0000.0.0
Codes		
	MPACT SPEED ESTIMATOR	CRUSH
(8) NOT APPLICABLE (9) UNKNOWN	(1) INVESTIGATOR (2) DRIVER (3) POLICE	(998) NOT APPLICABLE (NO VEHICLE/DAMAGE) (999) UNKNOWN
IMPACT SPEED	(4) "CRASH" PROGRAM (5) OTHER COMPUTER PROGRAM	CDC
(998) NOT APPLICABLE (999) UNKNOWN	SPECIFY:	(9800000) NOT APPLICABLE (9900000) UNKNOWN

BEST AVAILABLE COPY **Duplicate columns 1-8** Module D A Format 0 1 12 DAMAGE DA-2 from the previous card. MAXIMUM SHEET METAL CRUSH (cm) (999) - UNKNOWN FRONT $O_{13} 3_{15}$ 004 RIGHT SIDE O O O $\frac{O}{Z}$ $\frac{O}{Z}$ REAR LEFT SIDE <u>O</u> <u>O</u> <u>O</u> <u>27</u> 000 **ROOF OTHER** CHRONOLOGICAL SEQUENCE OF DAMAGE/INJURY PRODUCING CRASH EVENTS FOR CASE VEHICLE DO YOU KNOW THIS TABLE TO BE IN CHRONOLOGICAL ORDER? NOTE: IF CHRONOLOGICAL ORDER IS UNKNOWN, EVENT ORDER IS OPTIONAL. (0) NO (1) YES

EVENT NUMBER	IMPACT LOCATION (1) ON ROADWAY (2) SHOULDER/MEDIAN/GORE (3) ON ROADSIDE (4) OUTSIDE ROADSIDE RIGHT-OF-WAY (5) OTHER (6) OFF ROADWAY, LOC. UNK. (9) UNKNOWN	IMPACT CONFIGURATION FOR CODES, SEE TABLE ON PAGE DA-3.	OBJECT/VEHICLE CONTACTED FOR CODES, SEE TABLE ON PAGE DA-4.
# 1	1 32	13	28
#2		<u>43</u>	<u>2 8</u>
#3	42		
#4	47	49	
#5	52		
#6	57	 59	
#7	<u>es</u>		66

:

DAMAGE DA-3

CODES FOR IMPACT CONFIGURATION

FRONT OF CASE VEHICLE

- (11) AND FRONT OF CONTACTED VEHICLE
- (13) AND SIDE OF CONTACTED VEHICLE
- (14) AND REAR OF CONTACTED VEHICLE
- (16) ENDSWIPED BY CONTACTED VEHICLE
- (17) AND OBJECT
- (19) AND UNKNOWN OTHER VEHICLE CONFIGURATION

LEFT SIDE OF CASE VEHICLE

- (21) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (22) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (23) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (24) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (25) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (26) SIDESWIPED BY CONTACTED VEHICLE
- (27) AND OBJECT
- (29) AND UNKNOWN OTHER VEHICLE CONFIGURATION

REAR OF CASE VEHICLE

- (31) AND FRONT OF CONTACTED VEHICLE
- (33) AND SIDE OF CONTACTED VEHICLE
- (34) AND REAR OF CONTACTED VEHICLE
- (36) ENDSWIPED BY CONTACTED VEHICLE
- (37) AND OBJECT
- (39) AND UNKNOWN OTHER VEHICLE CONFIGURATION

<u>RIGHT SIDE</u> OF CASE VEHICLE

- (41) AND <u>FRONT</u> OF CONTACTED VEHICLE (TYPE T) (42) AND <u>FRONT</u> OF CONTACTED VEHICLE (TYPE L)
- (43) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (44) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (45) AND REAR OF CONTACTED VEHICLE (TYPE L)
 (46) SIDESWIPED BY CONTACTED VEHICLE
- (47) AND OBJECT
- (49) AND UNKNOWN OTHER VEHICLE CONFIGURATION

OTHER

- (57) VEHICLE TO OBJECT
- (58) VEHICLE TO VEHICLE
- (59) VEHICLE TO VEHICLE, CONFIGURATION UNKNOWN

ROLLOVER

- (61) LESS THAN 360°
- (62) 360° OR MORE
- (69) DETAILS UNKNOWN

UNKNOWN

(99) IMPACT TYPE UNKNOWN

DAMAGE DA-4

CODES FOR VEHICLE/OBJECT CONTACTED

VEHICLE/OBJECT GROUPS

- NO OBJECT (00)
- (01) (39) PASSENGER VEHICLE & TRUCK
- (40) (69) OTHER VEHICLE
- (70) (76) PEDESTRIAN & ON-ROADWAY OBJECT
- (77) (97) OFF-ROADWAY OBJECT
- (98)OTHER (DESCRIBE)
- (99) UNKNOWN

PASSENGER VEHICLE

- (02) LARGE
- (03) LIMOUSINE
- (17) PICKUP
- (20) UNKNOWN PASSENGER VEHICLE BODY
- (24) SUB-MINI
- (25) MINI
- (26) SUB-COMPACT
- (27) COMPACT
- (28) INTERMEDIATE
- (29) FULL

SIZE

WHEELBASE

SUB-MINI	< 2286 mm (< 90°)
MINI	2286 - 2412 mm (90° - 94.9°)
SUB-COMPACT	2413 - 2539 mm (95" - 99.9")
COMPACT	2540 - 2666 mm (100° - 104.9°)
INTERMEDIATE	2667 - 2793 mm (105° - 109.9°)
FULL	2794 - 2920 mm (110° - 114.9°)
LARGE	2921 - 3174 mm (115° - 124 9°)

LIMOUSINE > 3175 mm (> 125°)

MULTIPURPOSE PASSENGER VEHICLE

- (11) SMALL VAN (MINI)
- (12) PICKUP
- (14) SMALL UTILITY (WHEELBASE LESS THAN 107", E.G. JEEP, BRONCO)
- (15) LARGE UTILITY (WHEELBASE MORE THAN 107". E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (17) PICKUP CAR WITH CANOPY/SHELL COVER
- (21) MOTOR HOME
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (23) PICKUP CAR WITH SLIDE-IN CAMPER
- (31) CHASSIS-MOUNTED CAMPER

TRUCK

- (11) SMALL VAN (E.G. ECONOLINE)
- (12) PICKUP TRUCK
- (13) UNKNOWN LIGHT TRUCK
- (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (22) PICKUP TRUCK WITH SUDE-IN CAMPER
- (30) UNKNOWN TRUCK TYPE
- (31) CHASSIS-MOUNTED CAMPER
- (33) DELIVERY VAN (WALK-IN)
- (34) STRAIGHT TRUCK
- (35) TRUCK-TRACTOR (BOBTAIL)
- (36) CHASSIS-CAB
- (37) UNKNOWN HEAVY TRUCK
- (38) TRACTOR & SEMI-TRAILER (SEMI)
- (39) TRUCK (OR SEMI) & FULL TRAILER(S)

BUS

- (40) UNKNOWN BUS TYPE
- (41) SCHOOL BUS
- (42) INTERCITY BUS (BETWEEN CITIES)
- (43) TRANSIT BUS (INTRACITY)
- (44) STREETCAR (ON TRACKS)

MOTORCYCLE

- (50) UNKNOWN MOTORCYCLE TYPE
- (51) 1 75 ∞
- (52) 76 125 cc
- (53) 126 250 €
- (54) 251 500 cc
- (55) 501 750 ∞
- (56) 751 ∞ +
- (57) 3-WHEELS (OR WITH SIDECAR)

SPECIAL PURPOSE VEHICLE

- (60) UNKNOWN/OTHER SPECIAL VEHICLE (DESCRIBE)
- (61) SNOWMOBILE
- (62) ATV (ALL TERRAIN VEHICLE)
- (63) AMPHIBIOUS VEHICLE
- (64) FARM VEHICLE
- (65) CONSTRUCTION VEHICLE
- (66) TRAILER, PRIVATE (CAMPER)
- (67) TRAILER, COMMERCIAL (CARGO)
- (68) TRAIN (CARS)
- (69) LOCOMOTIVE (ENGINE, SWITCHER)

OBJECT

- (70) PEDESTRIAN
- (71) BICYCLIST, OTHER PEDALCYCLIST
- (72) PEDESTRIAN CONVEYANCE (E.G. PERSON RIDING ANIMAL, CART)
- (73) LARGE ANIMAL
- (74) FALLEN OBJECT (E.G. OBJECT DISLODGED FROM OTHER VEHICLE, FALLEN TREE, ROCKS)
- (75) ROCKS
- (76) CONSTRUCTION EQUIPMENT (EXCLUDING (65))
- (77) SIGN POST, UTILITY POLE, TREE...
- (78) DITCH
- (79) EMBANKMENT, SNOWBANK, RR TRACKS RR X
- (80) GROUND (ROLLOVER ONLY)
- (81) CURB (DAMAGE PRODUCING IMPACTS ONLY)
- (82) CULVERT
- (83) FENCE
- (84) HYDRANT, SHORT POST, STUMP
- (85) SMALL POST/TREE, RURAL MAIL BOX, MILE MARKER, DELINEATOR
- (86) BUILDING
- (87) PIER, PILLAR, BRIDGE SUPPORT
- (88) ABUTMENT, RETAINING WALL
- (89) BRIDGE RAIL
- (90) GUARD RAIL, LEADING SECTION
- (91) GUARD RAIL, MIDDLE OR UNKNOWN (92) GUARD RAIL, TRAILING SECTION (93) GUARD POST (TIMBER, METAL, CONCRETE)

- (94) CABLE, FENCE BARRIER
- (95) CONCRETE BARRIER (MEDIAN)
- (96) IMPACT ATTENUATOR
- (97) BREAKAWAY FEATURES

	Format 0 1 12		SH RECONSTRUC OT AV	CTION CR-1
	CASE VEHICLE F	PRIMARY IMPACT	CASE VEHICLE SE	CONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13		<u>Z</u>	
ΔV (km/h) TOTAL	0 2 0	$\frac{0}{32} \frac{2}{33} \frac{9}{34}$	48 49 50	9
LONGITUDINAL*	<u>- 020</u>	<u>-005</u>	9	9
LATERAL*	-003	±029	9	9
NOTE: THESE AV COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 58	73 76
EXAMPLES: 10 km/h = ± <u>0</u> 1 <u>0</u> -7 km/h = <u>- 0</u> <u>0</u> Z		-		
ENERGY DISSIPATED BY CRUSH (kj)	<u>O</u> <u>O</u> <u>7</u> <u>3</u>	0025	$\frac{9}{59}$ ${}$ ${62}$	9
RECONSTRUCTION				
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	22		08	
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64	
NOT RECONSTRUCTED BECAUSE				
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED				
MODE				
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	31		<u>5</u>	
COMPUTER PROGRAM SPECIFY:				

CRASH RECONSTRUCTION CR-2 Duplicate columns 1-8 Module C R Format 0 2 from the previous card. for EBS CASE VEHICLE SECONDARY IMPACT CASE VEHICLE PRIMARY IMPACT CASE CONTACTED CASE CONTACTED **VEHICLE VEHICLE VEHICLE VEHICLE EVENT NUMBER** EBS (km/h) TOTAL LONGITUDINAL* LATERAL* NOTE: THESE EBS COMPONENTS MUST INCLUDE SIGN. EXAMPLES: 10 km/h = ± 0 1 0 -7 km/h = <u>- Q Q Z</u> **ENERGY DISSIPATED BY** 0025 0073 CRUSH (kj) RECONSTRUCTION (01) RECONSTRUCTED, UNKNOWN <u>Z</u> <u>Z</u> CONFIDENCE LEVEL (21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL NOT RECONSTRUCTED BECAUSE (02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ **OVERRIDE** (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT **INSPECTED** MODE (1) CDC ONLY 5 65 (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & **DETAILED DAMAGE** (5) NOT RECONSTRUCTED **COMPUTER PROGRAM** SPECIFY:_

BEST AVAILABLE COPY CRASH RECONSTRUCTION Module <u>C</u> <u>R</u> Format <u>0</u> <u>3</u> Duplicate columns 1-8 CR-3 from the previous card. NOTES: 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS. CASE VEHICLE 2. MEASURE C_1 TO C_6 FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS. LOCATOR 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG. 4. USE THE CENTER OF THE WHEELBASE AS THE CG. Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts. Specific Impact No. Location of Direct Damage Location of Field L Begin Rt. BC III cm to Ct to BC FRONT 39cm forward of Rt. Rem Axle 2 C6 C5 PLANE: C2 (1) Bumper (2) Above Bumper (3) Sill (4) Above Sill (5) Other (9) Unknown CRUSH PROFILE IN CENTIMETERS NOTE: Each line in the table below is a separate record (card). Duplicate columns 1 - 12 for each completed line. Specific Plane **Direct Damage** Impact of Impact Field Length C_1 C₄ C₆ C_2 C_3 ±D C_5 Number C-Measur. (DDL) Crush /// 7 2 31 34 +37 - 3 -8 -16 -3 -3 -16 75 000 000 028 031 007 030 031 13 14 15 16 17 18 19 20 1 24 25 26 1 27 28 29 | 30 31 32 | 33 34 35 | 36 37 38 | 39 40 41 | 42 43 44 45 2 Ч

Ö\$ 4

019


999

999 999 999 999

2

CR-4

CRASH RECONSTRUCTION Duplicate columns 1-8 Module C R Format 0 from the previous card. 10 NOTES: 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS. OTHER VEHICLE 2. MEASURE C $_{\rm 1}$ TO C $_{\rm 6}$ FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS. LOCATOR 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG. 4. USE THE CENTER OF THE WHEELBASE AS THE CG. Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts. Location of Field L Specific Impact No. Location of Direct Damage Begin Lt. ft. BC 121cm REARWARD Begin Lt. fo BC 124 cm Reakward Begin Lt. RA. BC 20 cm forward Begin Lt. RR BC C6 **C**5



UDL

PLANE:

- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill
- (5) Other
- (9) Unknown

CRUSH PROFILE IN CENTIMETERS

	NOTE: Each	line in the tab		separate rec				umns 1 - 1	2 for each	complete	d line.
Specific Impact Number	Plane of Impact C-Measur.	Direct Length (DDL)	Damage Max Crush	Field L	C ₁	C ₂	C ₃	C ₄	C ₅	C ₆	±D
	4	121	19	124	0	5	10	17	13	6	+182
1	4	/2/ 15 16 17	019	124	000		0/0	0/7	0/3	006	+ 18Z
2	4	20	3	23	23 20	21 20 29	30 31 32	33 34 33	30 37 30	33 40 41	42 43 44 43
2	4	020	003	023	999	999	499	999	999	999	-999

	W T Format 0 11		WHEELS AND TIRES WT-1
WHEELSDAMAGED (0) NO (1) YES (9) UNKNOWN	LF flat RF RR LR	<u>O</u> 13 <u>O</u> O <u>D</u> 16	SIZE (NOT DOT CODE. IF UNKNOWN, USE 9'S) LF $\frac{P}{2}$ $\frac{2}{4}$ $\frac{4}{5}$ $\frac{7}{5}$ $\frac{8}{8}$ $\frac{1}{45}$ $\frac{6}{45}$
TIRE TREAD TYPE (1) REGULAR (2) SNOW (3) SLICKS (4) ALL WEATHER (MS) (7) OTHER: (9) UNKNOWN	LF RF RR LR	4 4 4 20	LR 55
CARCASS CONSTRUCTION (1) BIAS (2) BELTED BIAS (3) RADIAL (4) ELLIPTICAL (5) HI PRESSURE SPARE (6) SPACE SAVER SPARE (7) OTHER: (9) UNKNOWN	LF RF RR LR	M 2 3 3 2 2	
IF VEHICLE IS EQUIPPED WITH DUA WHEELS, COMPLETE FOR OUTER V AND MAKE NOTES ON INNER WHEE NOTES:	VHEE LS E LS .	——————————————————————————————————————	-

Duplicate columns 1-8 from the previous card. Module F T Formula	ormat <u>0 1</u>	FUEL AND FUEL TANKS	FT-1
TYPE OF PROPULSIVE FUEL (1) GASOLINE (2) DIESEL OIL (3) LPG (4) ELECTRIC (7) OTHER: (9) UNKNOWN	13	AUXILIARY TANK TYPE (1) OEM TANK (2) AFTER MARKET TANK (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	§ 21
MAIN TANK LOCATION	122	AUXILIARY TANK LOCATION	8 8 E
MAIN FILLER CAP LOCATION	1 1 3	AUXILIARY FILLER CAP LOCATION	8 8 S
MAIN TANK MATERIAL	1 20	AUXILIARY TANK MATERIAL	§ 28

TANK AND FILLER CAP LOCATION CODES

FIRST DIGIT (LONGITUDINAL)

- (1) BEHIND KICK-UP
- (2) IN KICK-UP
- (3) BETWEEN KICK-UP & COWL
- (4) FORWARD OF COWL
 (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

SECOND DIGIT (LATERAL)

- (1) LEFT OF FRAME
- (2) WITHIN FRAME OR CENTERED
- (3) RIGHT OF FRAME
- (4) DUAL, RIGHT & LEFT TANKS
 (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

THIRD DIGIT (VERTICAL)

- (1) BELOW FRAME
- (2) WITHIN FRAME OR CENTERED
- (3) ABOVE FRAME (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

TANK MATERIAL CODES

- (1) STEEL
- (2) ALUMINUM
- (3) PLASTIC
- (7) OTHER
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

BEST AVAILABLE COPY FUEL LEAKAGE Module F _ L Format 0 _ 1 FL-1 Duplicate columns 1-8 from the previous card. 10 11 12 DID FUEL LEAKAGE RESULT FROM A CRASH EVENT (0) NO KNOWN LEAKAGE SKIP PAGE. (1) YES <u>COMPLETE</u> PAGE. Ш Ш IV **LEAKING** I FAK COMPONENT TYPE OF **SEVERITY** LOCATION **EVENT** NUMBER COMPONENT SOURCE DAMAGE OF LEAK OF DAMAGE NUMBER #1 14 15 21 #2 23 29 #3 31 37 #4 39 45 #5 46 47 53 LEAKING COMPONENT IV SEVERITY OF DAMAGE **TANK AREA** EEC SYSTEM (CONTINUED) (1) MINOR (2) MODERATE (11) MAIN FUEL TANK (INCLUDING (33) VAPOR RECOVERY HOSES (3) SEVERE VAPOR RECOVERY DOME) (CANISTER TO CARBURETOR) (4) DISCONNECTED/DEFEATED (12) AUXILIARY FUEL TANK (34) LIQUID-VAPOR SEPARATOR (9) UNKNOWN (13) MAIN TANK FILLER TUBE (UNLESS PART OF TANK) (14) MAIN TANK CAP (GAS CAP) (35) CANISTER (15) AUXILIARY TANK FILLER TUBE (39) EEC SYSTEM, DETAILS V LOCATION OF LEAK (16) AUXILIARY TANK CAP (GAS CAP) UNKNOWN (19) TANK AREA, DETAILS UNKNOWN FIRST DIGIT (LONGITUDINAL LOCATION) (49) ENGINE COMPARTMENT. **DELIVERY SYSTEM** COMPONENT UNKNOWN (1) F, FORWARD OF COWL (99) COMPONENT UNKNOWN (2) P. BETWEEN COWL & (21) FUEL FEED LINE (MAIN TANK REAR BULKHEAD TO FUEL PUMP) (3) B, BEHIND REAR BULKHEAD (22) FUEL FEED LINE (AUXILIARY (4) Y. F. & P II COMPONENT SOURCE TANK TO FUEL PUMP) (5) Z, P, & B (23) FUEL RETURN LINE (FUEL (6) D. DISTRIBUTED PUMP TO TANK) (1) OEM (F. P & B) (24) INLINE FUEL FILTER (2) AFTER MARKET (9) UNKNOWN (25) FUEL LINE (PUMP TO (9) UNKNOWN CARBURETOR OR INJECTOR PUMP) (26) CARBURETOR TO INJECTOR PUMP **SECOND DIGIT** (27) FUEL PUMP (LATERAL LOCATION) III TYPE OF DAMAGE (29) DELIVERY SYSTEM, DETAILS UNKNOWN (1) L, LEFT

EVAPORATIVE EMISSION CONTROL SYSTEM

- (31) ATMOSPHERIC VENT PIPE (NON-EEC EQUIPPED)
- (32) EEC PIPE (VAPOR CANISTER TO CARBURETOR)

- (1) DENTED/CRUSHED (2) PUNCTURED
- (3) RUPTURED
- (4) SEVERED/GROSS TEARS
- (5) DISCONNECTED/DEFEATED
- (9) UNKNOWN

- (2) C, CENTER
- (3) R, RIGHT
- (4) Y. LEFT CENTER (L & C)
- (5) Z, RIGHT CENTER (R&C)
- (6) D, DISTRIBUTED (F. P & B)
- (9) UNKNOWN

Duplicate columns 1-8 Module F R Format 0 10 110 110 110 110 110 110 110 110 1		FIRE	FR-1
WAS THERE FIRE IN (0) NO <u>SKIP</u> PAC (1) YES <u>COMPLE</u>	GE.	CASE VEHICLE?	
DID FIRE START IN CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	14	SEVERITY OF FIRE DAMAGE (1) MINOR (2) MODERATE (3) SEVERE (9) UNKNOWN	16
FLAME PROPOGATION RATE (1) RAPID/EXPLOSIVE (2) SLOW/MODERATE (9) UNKNOWN	15	DID AN INJURY TO CASE VEHICLE OCCUPANT RESULT FROM FIRE IN OR ON CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	17

PROVIDE NOTES IF FIRE OCCURRED.

Duplicate columns 1-8 from the previous card. Module E D Format 0 11	1 12	EXTERIOR DAMAGE	ED-1
HOOD PERFORMANCE		STEERING COL FLEXIBLE COUPLING	
FOR THE FOLLOWING, USE CODES:		FLEXIBLE COUPLING TYPE	
(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN		(0) NONE (1) FLEXIBLE MATERIAL (2) POT (3) SINGLE U-JOINT (4) DOUBLE U-JOINT (5) FLEXIBLE CABLE (6) COMBINATION OF ABOVE (CIRCLE EACH)	<u>9</u> 26
HOOD LATCH(ES)RELEASED	<u>D</u>	(7) OTHER:	
-DAMAGED	14	COUPLING DAMAGED	9
JAMMED	15	(USE CODES FROM <u>HOOD</u> - <u>PERFORMANCE</u>) -SEPARATED (COMPLETE)	9 28
HOOD HINGESLEFT, DAMAGED	<u>D</u>		
-LEFT, SEPARATED (COMPLETE)	8 17		
-RIGHT, DAMAGED	0	ENG COMPART TELESCOPING UNIT	
-RIGHT, SEPARATED		TYPE OF UNIT	
(COMPLETE) HOOD REMAINED ON VEHICLE	19	(00) NONE INSTALLED (01) - (07) SEE UNITS ON PAGE ED-2 (88) NOT COLLECTED (97) OTHER:	8 8
REAR EDGE OF HOODELEVATED	1 21	ORIGINAL LENGTH (mm)	
-CONTACTED WINDSHIELD	0 22	F (OR H):	
-PENETRATED WINDSHIELD	8/23	TELESCOPED LENGTH (mm)	
HOOD LATCH LOCATION		G:	
(1) FRONT OF VEHICLE (2) COWL AREA (3) SIDE (8) NOT APPLICABLE (9) UNKNOWN	1 24	DIFFERENCE (mm) F (OR H) - G (IF LESS THAN 15mm, ENTER *000*.) (888) NOT COLLECTED	
ENGINE OR TRANSMISSION MOUNT SEPARATION (COMPLETE) (0) NO (1) YES (9) UNKNOWN	<u>O</u> 25		8 8 3

		EXTERIOR DAMAGE	ED-2
LEFT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>Q</u>	LEFT DOORS HOW DID DOORS OPEN DURING COLLISION?	
LEFT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		USE CODES: (0) DOOR DID NOT OPEN OPENED BECAUSE OF (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN	
-A-PILLAR, UPPER	<u>D</u> 35	(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN -FRONT	0 43
LOWER	<u>Q</u> 36	-REAR	0
LOWER	37 <u>O</u> 38	DOORS JAMMED CLOSED- USE CODES: (0) NO	
-C-PILLAR, UPPER	<u>Q</u>	(1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN -FRONT	
LOWER	<u>Q</u>	-PHONT	0 45 0 46
-D-PILLAR, UPPER	<u>Q</u>		
LOWER	<u>Q</u>	•	

		EXTERIOR DAMAGE	ED-3
		OTHER REAR DAMAGE	;
REAR DOOR REAR DOOR TYPE (0) NO DOOR (INCLUDES PICKUPS) (1) HATCHBACK (2) ONE-WAY TAILGATE (3) TWO-WAY TAILGATE	<u>6</u>	WAS PARTITION TO LUGGAGE AREA DAMAGED DURING COLLISION? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	50
 (4) CLAMSHELL/DISAPPEARING TAILGATE (5) SINGLE DOOR (6) DOUBLE DOOR (9) UNKNOWN 		SPARE TIRE (0) NO SPARE TIRE	. 8
Hatchback		(1) NOT ATTACHED BEFORE COLLISION (2) ATTACHED, NOT SEPARATED IN COLLISION (3) ATTACHED, SEPARATED DUE TO COLLISION (8) NOT COLLECTED (9) UNKNOWN	51
One-way Two-way Or Or Or Or Or Or Or Or Or O		TRAILER HITCH TYPE	
Clamshell		(0) NO HITCH BALL-AND-SOCKET TYPES (1) TEMPORARY FRAMEWORK (E.G.	4 52
Single door		RENTAL CLAMP-ON) (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK) (3) BUMPER-AND-FRAME (BUT NON-EQUALIZING) (4) LOAD EQUALIZING	
Double door		OTHER TYPES	
HOW DID DOOR OPEN DURING COLLISION?		(5) RING-AND-PINTLE (6) FIFTH-WHEEL (INCL. P/U) (7) OTHER (E.G. CLEVIS-AND-PIN)	
(0) DOOR DID NOT OPEN OPENED BECAUSE OF	<u></u>	(8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED	
(1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN DOOR JAMMED CLOSED		TRAILER TYPE (AT TIME OF COLLISION) (0) NO TRAILER (1) TRAVEL-TRAILER/CAMPER (2) MOBILE HOME (3) BOAT/SNOWMOBILE/ATV TRAILER (4) UTILITY TRAILER (5) TOWED CAR (7) OTHER: (8) TRAILER, TYPE UNKNOWN (9) UNKNOWN	<u>O</u> s3
(0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	<u>O</u>		


		EXTERIOR DAMAGE	ED-4
RIGHT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>Q</u>	RIGHT DOORS HOW DID DOORS OPEN DURING COLLISION? USE CODES:	
RIGHT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		(00) DOOR DID NOT OPEN OPENED BECAUSE OF (01) HINGE AREA SEPARATION (02) DOOR-LATCH SEPARATION (03) LATCH-STRIKER SEPARATION (04) STRIKER-PILLAR SEPARATION (05) BODY DISTORTION (06) COMBINATION OF ABOVE (CIRCLE EACH) (07) OPENED, REASON UNKNOWN (11) VAN RIGHT-REAR DOOR OPENED (ANY MECHANISM)	
-A-PILLAR, UPPER	<u>O</u> 55	(98) NOT APPLICABLE (NO DOOR) (99) UNKNOWN -FRONT	<u>5</u> 0
LOWER -B-PILLAR, UPPER	56	-REAR	65 66
LOWER	58	DOORS JAMMED CLOSED- USE CODES: (0) NO (1) YES	
-C-PILLAR, UPPER	<u>O</u> 59	(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN -FRONT	<u>O</u>
LOWER -D-PILLAR, UPPER	0 60	-REAR	<u>()</u>
LOWER	61	VAN REAR DOOR TYPE (0) VAN, NO REAR DOOR (1) TRACK (SLIDING) - RIGHT SIDE (2) SINGLE-HINGED - RIGHT SIDE (3) DOUBLE-HINGED - RIGHT SIDE (4) TRACK (SLIDING) - RIGHT & LEFT SIDE (5) SINGLE-HINGED - RIGHT & LEFT SIDE (6) DOUBLE-HINGED - RIGHT & LEFT SIDE (7) TRACK AND HINGED COMBINATION (8) NOT APPLICABLE (NOT A VAN) (9) UNKNOWN	<u>8</u>

		EXTERIOR DAMAGE	ED)-5
WINDSHIELD DAMAGE		WINDSHIELD MARK ON CASE VEHICL	E:	
WINDSHIELD CRACKED		· .		
(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	70			
WINDSHIELD BROKEN (PLASTIC INTERLAYER TORN)				
(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	8			
CRACKED OR BROKEN BY OCCUPANT CONTACT				
(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	72	WINDSHIELD CODE		
EXTENT OF BOND SEPARATION		(97) DESCRIBED BUT NOT CODED (98) NOT APPLICABLE (NO WINDSHIELD) (99) UNKNOWN	7	\ <u>U</u>
(0) NONE (1) 1 - 20% (2) 21 - 40 (3) 41 - 60 (4) 61 - 80	73	ROOF DID T-ROOF/SUN ROOF OPEN DURING COLLISION?		
(5) 81 - 99 (6) TOTAL (7) SEPARATED, AMOUNT UNKNOWN (8) NOT APPLICABLE		(0) NO (1) YES (8) NOT APPLICABLE (NOT A T-ROOF OR SUN ROOF)		8/76
(9) UNKNOWN LOCATE AREA OF WINDSHIELD IN & HORIZONTAL) ON THIS DIAGRA	TEREST OF	(9) UNKNOWN R DAMAGE WITH DIMENSIONS (VERTICAL WINDSHIELD AS VIEWED FROM INSIDE.		
	ı			

Duplicate columns 1-8 from the previous card. Module S C Format 10	0 1	STEERING WHEEL AND COLUMN	3U-1
STEERING WHEEL		STEERING WHEEL POSITION TAT TIME OF COLLISION	· · !
STEERING WHEEL RIM DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	<u>Q</u>	IN WHAT O'CLOCK POSITION WAS THE NORMAL TOP OF THE WHEEL POINTED WHEN THE COLLISION OCCURRED? EXAMPLES O'CLOCK = 1 2 O'CLOCK = 0 2	
NUMBER OF STEERING WHEEL SPOKES (9) UNKNOWN	4	(NORMAL STRAIGHT AMEAD) O'CLOCK - 99	
STEERING WHL SPOKE DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	15	STEERING WHEEL ENERGY ABSORBING DEVICE (1) EXAMPLES: BARRACUDA, 70-74 CHALLENGER, 70-74 CAPRI, 71-77	
STEERING COLUMN OPTIONS		(2) EXAMPLES: CMMI, 78 - HORIZON, 78 -	
TILT FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED, UNK POSITION (2) UP (3) MIDDLE (4) LOWER (9) UNKNOWN IF EQUIPPED	3 16	TYPE OF DEVICE (0) NONE (1) CONVOLUTED OR MESH CYLINDER (2) DEEP DISH STEERING WHEEL (7) OTHER: (8) NOT COLLECTED (9) UNKNOWN IF EQUIPPED ORIGINAL DIMENSION (mm.)	8 19
SWING-AWAY FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u>D</u>	A: DAMAGE DIMENSION (mm) B: DIFFERENCE (mm)	
TELESCOPING FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u>O</u> 18	A - B (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO MEASURE (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8

		STEERING WHEEL AND COLUMN	SC-2
STEERING COLUMN ENERGY ABSORBING DEVICE TYPE OF DEVICE * (IF 27 OR 28) (00) NOT EQUIPPED (88) NOT COLLECTED (99) UNKNOWN ORIGINAL LENGTH (mm) C:	8 8 23 24	STEERING WHEEL (CONTINUED) STEERING WHEEL HUB DAMAGE (0) NONE (1) OCCUPANT CONTACT (2) AIRBAG (3) OTHER (9) UNKNOWN	<u>0</u>
COMPRESSED LENGTH (mm) D: BRACKET DEFLECTION (IF CODE 36, 48, OR 49 ABOVE) OR COMPRESSION (OR EXTRUSION) (mm) C - D (OR E) (TOLERANCE: ±10) (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN * (ADD A & B FOR TOTAL COMPRESSION) SHEAR CAPSULE SEPARATION (mm) S (USE AVG. OF LEFT & RIGHT CAPSULES.) LT:	8 8 8 27		
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT SEPARATION (992) SEPARATED, AMOUNT UNKNOWN (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8		
COLUMN VERTICAL ROTATION (0) NO APPARENT ROTATION (1) UPWARD APPARENT ROTATION (2) DOWNWARD APPARENT ROTATION (9) UNKNOWN	<u>O</u> 31		
COLUMN LATERAL ROTATION (0) NO APPARENT ROTATION (1) LEFT APPARENT ROTATION (2) RIGHT APPARENT ROTATION (9) UNKNOWN	<u>Q</u>		

					*			INTRU	JSION	IT-1
					(All Measurements Are in Centimeters)					
Location Intrusion	of n	Intruded	l Component	Compar Value	ison e =	Intruded Value	=	Intrusion		Dominant Crush Direction
							=			
					_		=			
			· · · · · · · · · · · · · · · · · · ·		_		=			
					_		=			
	,				_		=			
					_		=			
			-1		_		=			
							=			
					_		=			
					_		=			
							=			
					_		=			
					` -		=			
							=			
					-		=			
					_		=			
	,		0	CCUPANT C	CONTACT	WORKSHEE	ET			
Contact	Co	Interior Occupant Component No. if Contacted Known if		Body Region if Known	5	Supporting Physical Evidence				Confidence Level of Contact Point
Α										
В										
С										
D										
E								•		
F										
G							, <u></u> ,	manana manana nga mga mga mga mga mga mga mga mga mga m		
н										
1										
J										



INTRUSION IT-3

CODES FOR COLUMN B, OCCUPANT SPACE NUMBER

OCCUPANT SPACE NUMBER IS A TWO-DIGIT CODE. THE USE OF THE CODE IS DETERMINED BY THE VEHICLE SEAT CONFIGURATION AT THE TIME OF THE ACCIDENT.

FIRST DIGIT

THE FIRST DIGIT (LEFT DIGIT) DENOTES THE SEAT ROW, WITH CODE VALUES FROM 1 TO 5.

SECOND DIGIT

THE SECOND DIGIT (RIGHT DIGIT) DENOTES THE POSITION ON THE SEAT AND, IN SOME INSTANCES, THE WIDTH OF THE SEAT.

(1)	LEFT	(3)	RIGHT	•••••	•••••••••••••••••••••••••••••••••••••••	INDIVIDU	JAL SEAT
(1)	LEFT	(2)	CENTER	(3)	RIGHT	BENCH:	FULL WIDTH 3 PASSENGER
(1)	LEFT	(2)	LEFT CENTER		RIGHT (3) RIGHT	BENCH:	FULL WIDTH 4 PASSENGER
(1)	LEFT	(2)	CENTER		RIGHT &	BENCH:	PARTIAL WIDTH, LEFT
	LEFT & SPACE	(2)	CENTER	(5)	RIGHT &	BENCH:	PARTIAL WIDTH, CENTERED
(4)	ENTIRE	/EH	ICLE WIDTH	•••••		CARGO	AREA

EXAMPLES

THE TWO FIGURES BELOW PROVIDE EXAMPLES OF THE OCCUPANT SPACE NUMBER.

PASSENGER CAR 5 PASSENGERS

VAN 12 PASSENGER CAPACITY

X			X	11			13	
x	X	X		ļ		21	22	25
X							32	35
X	X	X	X	41	42	46	43	

CODES FOR COLUMN F, MEASUREMENT AXIS

(X) X-AXIS (FORE & AFT)

(Y) Y-AXIS (LATERAL)

(Z) Z-AXIS (VERTICAL)

CODES FOR COLUMNS G, H, I & J, OCCUPANT & INJURY NUMBERS

OCCUPANT	INJURY	
NUMBER	NUMBER	CONTACT
(00)	(00)	NO CONTACT
(##)	(00)	CONTACT, NO INJURY
(97)	(99)	CONTACT, OCCUPANT UNKNOWN, INJURY UNKNOWN
(99)	(00) OR (99)	UNKNOWN IF CONTACT

INTRUSION IT-4

CODES FOR COLUMN C, INTRUDING COMPONENT OR OBJECT

NOTE: DO NOT CODE OBJECTS OTHER THAN COMPONENTS OF CASE VEHICLE.

INDIVIDUAL COMPONENT

INTERNAL

- (01) INSTRUMENT PANEL
- (02) FIRE WALL
- (03) TOE PAN
- (04) FLOOR PAN
- (05) STEERING COLUMN
- (06) WINDSHIELD
- (07) WINDSHIELD HEADER
- (08) A-PILLAR
- (09) DOOR PANEL OR SIDE PANEL
- (10) WINDOW FRAME
- (11) B-PILLAR
- (12) C-PILLAR
- (13) D-PILLAR
- (14) ROOF SIDE RAILS
- (15) ROOF OR CONVERTIBLE TOP
- (16) BACKLIGHT HEADER
- (17) FRONT SEAT-BACK SURFACE/ SEAT-BACK BACK SURFACE
- (18) SECOND SEAT-BACK SURFACE **SEAT-BACK BACK SURFACE**
- (19) THIRD SEAT-BACK SURFACE **SEAT-BACK BACK SURFACE**
- (20) FOURTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (21) FIFTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (22) BACK PANEL/BACK DOOR SURFACE
- (23) SEAT CUSHION SURFACE/EDGE
- (24) CONSOLE
- (25) OTHER (DESCRIBE)
- (26) UNKNOWN INTERNAL SURFACES
- (28) TRANSMISSION TUNNEL (HUMP)
- (29) SIDE FOOTWELL PANEL (KICKPANEL)
- (30) SILL

EXTERNAL

- (43) HOOD
- (44) OBJECT EXTERNAL TO PASSENGER COMPARTMENT BUT PART OF CASE VEHICLE
- (45) OUTSIDE SURFACE OF CASE VEHICLE
- (46) OTHER (E.G. SPARE TIRE. JACK. DESCRIBE.)
- (49) UNKNOWN EXTERNAL OBJECT

GROUPED FOR MASSIVE INTRUSION INTO AN OCCUPANT SPACE

USE ONLY IF ALL THESE COMPONENTS INTRUDED INTO A SINGLE OCCUPANT SPACE.

(50)WINDSHIELD HEADER A-PILLAR

ROOF SIDE RAIL

- (51)INSTRUMENT PANEL A-PILLAR DOOR PANEL
- (52)INSTRUMENT PANEL

A-PILLAR

WINDSHIELD HEADER

- (53)DOOR PANEL **B-PILLAR ROOF RAIL**
- (54)DOOR PANEL A-PILLAR **ROOF RAIL**
- (55)INSTRUMENT PANEL

FLOOR PAN A-PILLAR

DOOR FRAME

(56)ROOF RAIL

A-PILLAR

B-PILLAR

WINDOW FRAME

(57) ROOF RAIL

A-PILLAR

B-PILLAR

C-PILLAR

DOOR PANEL

(58)ROOF

ROOF RAIL WINDOW FRAME

DOOR PANEL

(59)BACKLIGHT HEADER

ROOF

C-PILLAR

THIRD SEAT-BACK

(60)ROOF **ROOF RAIL** A-PILLAR **B-PILLAR** C-PILLAR **WINDOW FRAME**

DOOR PANEL **FLOOR PAN**

(61)INSTRUMENT PANEL

TOE PAN

WINDSHIELD HEADER

A-PILLAR **ROOF RAIL** WINDOW FRAME

DOOR PANEL ROOF

(62)ROOF

ROOF RAIL C-PILLAR

WINDOW FRAME

FLOOR PAN SECOND SEAT

DOOR PANEL

(63)ROOF RAIL

ROOF

B-PILLAR

WINDOW FRAME FLOOR PAN

DOOR PANEL

SECOND SEAT

FRONT SEAT

(64)ROOF RAIL

ROOF OR CONVERTIBLE TOP A-PILLAR

B-PILLAR

WINDOW FRAME

WINDOW HEADER

(65)WINDSHIELD WINDSHIELD HEADER

ROOF SIDE RAIL

(66)WINDSHIELD WINDSHIELD HEADER A-PILLAR

(98)NOT APPLICABLE

(99)UNKNOWN

	columns 1-l previous can		⊥ <u>T</u>	Format 0	1 12			İnti	RUSION	IT-5
(0) N (1) Y	10 <u>00 NO</u>	UPANT COM TANSWER NEX B NEXT QUES SKIP PAGE	CT QUEST		7	O V		ION CATAS [*] COMPLETE PA SKIP PAGE.		14
from the	columns 1-6 previous card ach line in th		9 10	Format 0 11 arate record (12	olicate column	is 1 - 12 for eac	h completed li	ne. _.	****
J	NTRUSIO	CODES F	FOR B, F	NS IN THIS C F, G, H, I, J N PAGE IT-	ON PAGE		ON ROW; FR	ONT TO BAC		:S
A INTRUSION NUMBER	B OCC.	C INTRUDING COMPONENT OR OBJECT	D ASSOC. EVENT NO.		F MAXIMUM INTRUSION Y AXIS (cm)	_	OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
0 1										
02										
0 <u>3</u> 0 <u>4</u>										
<u>0 5</u>										
06										
0 7 NOTE: US	E ADDITIONAL	PAGE IF MORE TI	HAN 7 INTR	USIONS.						
	columns 1-8 previous card		<u> </u>	Format <u>0</u>	<u>3</u> 12					
ski SIDE	NO SIDE DOO P REMAINDEI DOOR INT SULTED F	TRUSION		IF DA DOO! INTRU NUMB!	R INTRUS SION	DOOR CO NON, CODE DAMAGED DMPONENT 1	DMPONENT E COMPONE DAMA COMPO	ENT AGED NENT 2	D IN INCRE CODES FOR COMPONE	
INTRUSI NUMBE	ER CAUSE	CODES FOR CAUSE:		A	_			<u> </u>	(0) NONE (1) A-PILLAR (2) B-PILLAR	:NIS
13	18	(1) DIRECT IMPACT (2) INDUCED DAMAGE (9) UNKNOWN	J	B		_	2:	9 ((3) C-PILLAR (4) LATCH/STR (5) HINGES (7) OTHER:	
13	• '	(S) SHRINGWI		D	_		37	((9) UNKNOWN	UABLE

Duplicate columns 1-8 from the previous card.

Module | T Format 0 2

INTRUSION

IT-6

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.

- ADDITIONAL PAGE -

INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES.

CODES FOR B, F, G, H, I, J ON PAGE IT-3

CODES FOR C ON PAGE IT-4

OCCUPANT CONTACT AND INJURY

							<u> </u>		1	
A INTRUSION NUMBER	OCC. SPACE NO.	C INTRUDING COMPONENT OR OBJECT			F MAXIMUM INTRUSION Y AXIS (cm)		H OCCUPANT NUMBER	INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
<u>0 8</u>										
0 9										
10										
11										
12.										
1 3										
14			_							
15			_							
16										
17										
<u> 1</u> <u>B</u>			-							
1 9			_							
20										
21										
2 2			_							
23										
24			_							
2 5										
										

Duplicate columns 1-8 from the previous card.	Module	1 D	Format <u>0</u> <u>1</u>	İN	TERIOR DAMAGE	D-1
со	(1)	NO YES NO, and	OCCUPANT CONTACT	(4) YES, and C (8) NOT APPL (9) UNKNOWN		
SIDES FRONT DOOR FRONT HARDWARE FRONT ARMREST FRONT GLASS REAR DOOR AREA REAR HARDWARE REAR ARMREST REAR GLASS ROOF SIDE RAIL B-PILLAR C-PILLAR D-PILLAR HEADLINING	(0) (1)	YES NO. and PIGHT O 12 O 20 O 22 O 22 O 25 O 25 O 25 O 25 O 2		(8) NOT APPL	ICABLE	
T-ROOF/SUN ROOF OTHER: *	98 <u>8</u> 41 <u>8</u> 42	Q30 96 26 4			REAR WINDOW WINDOW HEADER CONSOLES VERTICAL ROOF	67 67 69 69 70 71

^{*} MORE THAN ONE ITEM MAY BE NOTED.

Duplicate columns 1-8 from the previous card. Module S T 10		2 12	SEATS	,	ST-1
FRONT SEAT TYPE OF FRONT SEAT (00) NO SEAT (01) STANDARD BENCH (02) SPLIT BACK, 50-50 (03) SPLIT BACK, DRIVER WIDE (04) SPLIT BACK, PASS. WIDE (05) BUCKET (06) CAPTAIN'S CHAIR (07) INDIV. BENCH, 50-50 (08) INDIV. BENCH, DRIVER WIDE	DRIVER D 5 14	PASSENTR 0 5 15 16	FRONT SEAT-BACK SEAT-BACK TYPE (1) FORWARD FOLDING (2) RIGID (3) RECLINING (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	Driver 3	PASSENR 31
(09) INDIV. BENCH, PASS. WIDE (97) OTHER: (99) UNKNOWN TYPE OF SEAT MOUNT (1) STANDARD (2) PEDESTAL (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	<u>J</u>	18	SEAT-BACK LOCK TYPE (0) NONE (1) MANUAL (2) INERTIA (3) POWER (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	32	1 33
SWIVEL MECHANISM EQUIPPED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>D</u> .	<u>O</u> 20	LOCKS HELD (0) NO (1) YES (8) NOT APPLICABLE	1 34	35
ORIGINAL EQUIPMENT SEATS (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	1 21	1 22	(9) UNKNOWN RECLINER MECHANISM HELD (0) NO	T	<u> </u>
CONTACT OF SEAT BY REAR OCCUPANT (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>4</u> 23	8 24	(1) YES (8) NOT APPLICABLE (9) UNKNOWN	36	37
FRONT SEAT DAMAGE (0) NONE (1) BACKREST ONLY DAMAGED (2) CUSHION ONLY DAMAGED (3) BACKREST & CUSHION DAMAGED (8) NOT APPLICABLE (9) UNKNOWN	<u>O</u> 25	<u>O</u> 26	HEAD RESTRAINT HEAD RESTRAINT TYPE (0) NONE (1) ADJUSTABLE (2) INTEGRAL (3) NOT INTEGRAL, BUT CANNOT BE REMOVED (7) OTHER: (8) NOT APPLICABLE	38	39
CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	0 27	-	(9) UNKNOWN REMOVED PRE-CRASH (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>D</u>	D 41
FRONT SEAT ROTATION	0	0	ADJUSTMENT AT CRASH (1) UP (2) DOWN (8) NOT APPLICABLE (9) UNKNOWN	2/42	2 43
(0) NONE APPARENT (1) FORWARD APPARENT (2) REARWARD APPARENT (3) LEFT APPARENT (4) RIGHT APPARENT (5) MULTIPLE ROTATIONS SPECIFY (8) NOT APPLICABLE (9) UNKNOWN	28	29	HEAD RESTRAINT DAMAGE (0) NONE (1) DAMAGED BUT NOT SEPARATED (2) SEPARATED (8) NOT APPLICABLE (9) UNKNOWN	0 4	<u>O</u>

			Si	EATS S	ST-2
FRONT SEAT ADJUSTMENT	DRIVER	PASSENT	SECOND SEAT (CONT.)		
SEAT ADJUSTMENT TYPE (0) NONE (RIGID) (1) MANUAL (2) POWER (7) OTHER: (8) NOT APPLICABLE (NO SEAT) (9) UNKNOWN	2	47	(0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE		2
ADJUSTMENT PROVIDED (1) 2-WAY (2) 4-WAY (3) 6-WAY (7) OTHER: 8 - WAY (8) NOT APPLICABLE (9) UNKNOWN	7	49	(9) UNKNOWN IF EQUIPPED SECOND SEAT-BACK LOCKS	LEFT	Я і с нт
SEAT ADJUSTER DAMAGE (0) NONE (1) CHUCKING (FREE PLAY) (2) DEFORMED (RELEASED/JAMMED) (3) SEPARATED (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	<u>D</u>	<u>O</u> 51	FOR THE FOLLOWING, USE: (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN		0
SEAT ADJUSTER SEPARATION (0) NONE (1) SEPARATED AT FLOOR (2) SEPARATION OF ADJUSTER (3) SEPARATED AT SEAT (8) NOT APPLICABLE (9) UNKNOWN	<u>8</u>	53	LEFT OR CENTER, EQUIPPED LEFT OR CENTER, HELD (3) SEAT FOLDED DOWN RIGHT, EQUIPPED	61 63 00 65	D 28 4 - 66
PRE-CRASH POSITION (1) FORWARD (2) MIDDLE (3) REARWARD (8) NOT APPLICABLE (9) UNKNOWN	<u>2</u> 54	2 55	RIGHT, HELD (3) SEAT FOLDED DOWN THIRD SEAT	<u>&</u>	68
SECOND SEAT	LEFT	RIGHT	EQUIPPED	<u> </u>	1/70
TYPE OF SECOND SEAT (0) NONE (1) NON-FOLDING (2) FOLDING (3) CAPTAIN'S CHAIR (4) JUMP SEAT	2 56	2	BACKREST DAMAGED CUSHION DAMAGED	D 71 D 72	O 72 O 74
(5) INTEGRAL CHILD SEAT (6) LUGGAGE AREA ACCESS PANEL (9) UNKNOWN SECOND SEAT DAMAGE (0) NONE (1) BACKREST ONLY (DAMAGED OR LOOSENED) (2) CUSHION ONLY (DAMAGED OR LOOSENED) (3) BACKREST & CUSHION (DAMAGED OR LOOSENED) (4) INTEGRAL CHILD SEAT (PRIORITY CODE) (5) LUGGAGE AREA ACCESS PANEL (DAMAGED OR LOOSENED) (8) NOT APPLICABLE (9) UNKNOWN	<u>O</u> 58	59	VEHICLE EQUIPPED WITH REAR HEAD RESTRAINTS (0) NOT EQUIPPED (OR REMOVED) (1) EQUIPPED (2) EQUIPPED & DAMAGED (8) NOT APPLICABLE (NO REAR SEAT) (9) UNKNOWN Applies to any rear-seat position	7.	<u> </u> 5

Duplicate columns 1-8 from the previous card. Module A B Format C 9 10 1	1 12	AIRBAG	AB-
DRIVER SIDE		PASSENGER SIDE	:
LOCATION OF AIRBAG		-LOCATION OF AIRBAG	
STEERING WHEEL		INSTRUMENT PANEL (GLOVE BOX)	
EQUIPPED		EQUIPPED	
(0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	13	(0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	1
DEPLOYED		DEPLOYED	
(0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	14	(0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	177
CONDITION OF AIRBAG STEERING WHEEL		CONDITION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX)	
(0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE NOT EQUIPPED OR CONDITION	<u>Q</u>	(0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE MOT EQUIPPEDMOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	18
DRIVER SIDE AIRBAG		PASSENGER SIDE	
STEERING WHEEL		AIRBAG	
TETHER		INSTRUMENT PANEL (GLOVE BOX) TETHER	
(0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	19	(0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	21
MARKED BY CONTACT		MARKED BY CONTACT	
(0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	<u>D</u>	(0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	0 22

AIRBAG AB-2 AIRBAG NUMBER ON DRIVER SIDE: NOTE AND DESCRIBE ANY AIRBAG CONTACT OR **DAMAGE ON DIAGRAM BELOW:** 61 Wide 53 Tall 2 vent holes at 1121:00 Air tag flaps = 10.5 tall 7.5 cm wide AIRBAG NUMBER ON PASSENGER SIDE: NOTE AND DESCRIBE ANY AIRBAG CONTACT OR Vent holes at **DAMAGE ON DIAGRAM BELOW:** 3700 4 9:00 Seam -> Seam 57 wide 40cm tall

NOTE TO THE INVESTIGATOR:

THE FOLLOWING TWO SECTIONS,

OCCUPANT INFORMATION AND INJURY CLASSIFICATION,

ARE TO BE FILLED IN

FOR EACH CASE VEHICLE OCCUPANT,

WHETHER INJURED OR NOT.

IF THERE IS MORE THAN ONE OCCUPANT,
USE ADDITIONAL COPIES
OF PAGES OC-1, OC-2, OC-3,
AND IC-2 TO DESCRIBE THEM
AND ATTACH THE COPIES TO THIS REPORT.

Duplicate columns 1-8 from the previous card. Module O C Format 0 9 10 11		OCCUPANT INFORMATION	OC-1
OCCUPANT IDENTIFICATION OCCUPANT NUMBER ROLE OF OCCUPANT AT 1ST IMPACT (1) MOTOR VEHICLE DRIVER (2) MOTOR VEHICLE PASSENGER (NOT DRIVER) (9) UNKNOWN	<u>0</u> <u>1</u> 14 <u>1</u> 15	PHYSICAL DESCRIPTION AGE IN YEARS (00) LESS THAN 1 YEAR (98) 98 YEARS OR OLDER (99) UNKNOWN AGE IN MONTHS (00) LESS THAN 1 MONTH (25) 25 MONTHS OR OLDER (99) UNKNOWN	2 8 20 21 2 5 22 23
OCCUPANT POSITION ROW LOCATION (1) FRONT (2) SECOND (3) THIRD (4) FOURTH (7) OTHER: (8) EXTERNAL TO PASSENGER COMPARTMENT (E.G. BED OF PICKUP) (9) UNKNOWN	16	MASS (kg) (999) UNKNOWN (210 lb) HEIGHT (cm) (999) UNKNOWN (5 ft	O 95 24 25 26 1 8 0 27 28 29
LATERAL LOCATION (1) LEFT (2) LEFT CENTER (3) CENTER (4) RIGHT CENTER (5) RIGHT (6) ALL (LYING ON SEAT) (8) EXTERNAL TO PASSENGER COMPARTMENT (9) UNKNOWN	17	MEDICAL CONDITIONS TREATMENT/MORTALITY (00) NONE (01) FIRST AID AT SCENE (02) TREATED AT HOSPITAL/CLINIC BUT NOT ADMITTED (03) HOSPITALIZED FOR OBSERVATION LESS THAN 24 HOURS (04) HOSPITALIZED OVER 24 HOURS OR FOR SIGNIFICANT TREATMENT (05) FATAL, DEAD AT SCENE (06) FATAL, DOA	<u>O</u> D
POSTURE (10) SITTING ON SEAT (11) SITTING ON SEAT IN ABNORMAL POSITION (E.G. FEET ON DASH, SIDEWAYS) (12) SITTING ON CONSOLE (20) ON LAP OR IN ARMS (30) STANDING ON SEAT (40) STANDING ON FLOOR (47) STANDING, EXTERNAL TO PASSENGER COMPARTMENT (50) IN BASSINET (60) IN CHILD SEAT (65) IN CHILD HARNESS (70) LYING ON SEAT (80) LYING/SITTING ON PASSENGER FLOOR	1 0	(07) FATAL, DEAD WITHIN 24 HOURS (08) FATAL, DEAD 24 HOURS TO 31 DAYS LATER (09) FATAL, DEAD 31 DAYS TO 1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN INJURY SEVERITY SCORE (ISS) (99) UNKNOWN NON-IMPACT MED. CONDITIONS (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL)	<u>O</u> <u>O</u> <u>33</u> <u>34</u>
(83) LYING/SITTING ON OTHER OBJECT IN PASSENGER COMPARTMENT: (85) ON CARGO FLOOR/FOLDED SEAT-BACK (87) LYING/SITTING, EXTERNAL TO PASSENGER COMPARTMENT (97) OTHER: (99) UNKNOWN		(3) PRE-CRASH NON-FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH FATAL (DROWNING) (6) POST-CRASH NON-FATAL INJURY (7) OTHER: (8) COMBINATION OF ABOVE (CIRCLE EACH) (9) UNKNOWN	

		OCCUPANT INFORMATION	OC-2
MEDICAL CONDITIONS (CONT.)		CHILD SEAT TYPE	1
POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN	1 36	(00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN CHILD SEAT MAKE/MODEL	8 3
RESTRAINT SYSTEM			
ACTIVE RESTRAINT SYSTEM (0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN	3	EJECTION DEGREE OF EJECTION (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED	0
ACTIVE RESTRAINT SYSTEM USAGE (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN	38	AREA OF EJECTION (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, REAR (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, REAR OR TAILGATE (07) WINDSHIELD	9 8
PASSIVE RESTRAINT SYSTEM (0) NONE (1) AIRBAG INSTALLED (2) PASSIVE UPPER TORSO WITH KNEE BOLSTERS (3) PASSIVE UPPER TORSO	39	(08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED	
WITHOUT KNEE BOLSTERS (4) PASSIVE LAP & UPPER TORSO (5) AIRBAG INSTALLED & PASSIVE RESTRAINT (7) OTHER: (9) UNKNOWN		IN DETAIL BELOW:	
PASSIVE RESTRAINT SYSTEM USAGE (0) SYSTEM DEFEATED (1) AIRBAG NOT DEPLOYED (2) AIRBAG DEPLOYED (3) AIRBAG NOT REINSTALLED (4) PASSIVE UPPER TORSO USED (5) PASSIVE LAP & UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN	2 40	HEAD RESTRAINT HEAD RESTRAINT AVAILABLE FOR THIS POSITION (0) NOT EQUIPPED OR REMOVED (1) EQUIPPED	

		OCCUPANT INFORMATION OC-3			
OCCUPANT EYEWEAR (0) NONE (1) GLASSES (2) CONTACTS (3) BOTH GLASSES AND CONTACTS (4) OTHER (8) NOT APPLICABLE (9) UNKNOWN	\$	SOURCE OF INFORMATION (0) INTERVIEW (1) HOSPITAL (2) AUTOPSY (3) POLICE (4) OTHER (5) LAY CORONER/EXTERNAL EXAM (7) COMBINATION OF ABOVE (CIRCLE) (8) NOT APPLICABLE	O		

OCCUPANT INFORMATION OC-4 No Injury

Duplicate columns 1-8 from the previous card.

NOTE: USE ADDITIONAL PAGES IF NECESSARY.

Module 1 C Format 0 1 12


INJURY CLASSIFICATION IC-1

Occ	CUPANT	INJUR	y Clas	SIFICATION											
						PRIM	IARY (OIC		A	ssoc	IATE	010	!	COMMENT
OCCUPANT NUMBER	INJURY NUMBER	PROBAE START V IN 1ST C	BILITY (HORI WITH MOST CONTACT AF	N ORDER OF . ZONTALLY) . PROBABLE REA COLUMN. LE CONTACT	BODY REGION 1	ASPECT N	LESION 3	SYSTEM/ORGAN &	SEVERITY W	BODY REGION -	ASPECT O	LESION O	SYSTEMORGAN &	SEVERITY U	
3-14	15-16	17-18	19-20	COMMENTS	21	22	23	24	25	26	27	28	29	30	
					ļ —		_		_	_		_	_	-	
					-	_	-	_	_	_		_	_	_	
					_	_	_			_		_		_	
					_		_	_	_			_	_		
					_	<u>•</u>	_ 1	الم	_		_		_		
					1	17	V	_!	_	_	_				
					/_'			_	_			_			
			_\	~		_	_					_	_		
ach line			D	0											
umber for each ine			-+		-	_		-							
				•	-			-		-					
Occupa					-	_	_	_	-	_		·—	_	-	
Duplicate Occupant N					-	_			-		_	_	_		
ਤ 					-			_	-	_				-	
					-	_	_		-		_		_	-	
					-		_		-	_		_	_	-	
					-	_		_	-	_		_	_	-	
					-			_	_	_	_	_		-	
					_		_	_			_	_		_	

INJURY CLASSIFICATION IC-2

CODES FOR AREAS OF POSSIBLE OCCUPANT CONTACT

FRONT	OF PASSENGER COMPARTMENT	<u></u> .	SIDES	
	SUNVISOR, FITTING(S) &/OR TOP MOLDING		(20)	SURFACE OF SIDE INTERIOR
(12)			(19)	
			(13)	
(05)	INSTRUMENT PANEL (SPECIFIC AREA UNKNOWN)		(24)	
(54)	UPPER INSTRUMENT PANEL (X)		(= -,	·
(55)	MIDDLE INSTRUMENT PANEL (Y)		(22)	WINDOW GLASS (SIDE)
(56)	LOWER INSTRUMENT PANEL (Z)		(21)	· · · · · · · · · · · · · · · · · · ·
(81)	ASH TRAY (INSTRUMENT PANEL)		(,	·····5
(02)	GLOVE COMPARTMENT AREA		(26)	ROOF SIDE RAIL
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER			A-PILLAR
				B-PILLAR
(57)	BENEATH INSTRUMENT PANEL			C-PILLAR
(53)	PARCEL TRAY		(17)	D-PILLAR
(48)	KNEE RESTRAINT			- · · · · · · · · · · · · · · · · · · ·
(86)	VERTICAL CONSOLE		FLOOR	
			(40)	FLOOR
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)		(27)	CONSOLE ON FLOOR OR BETWEEN SEATS
			(44)	
(09)	STEERING ASSEMBLY (SPECIFIC AREA UNKNOWN)		(85)	
(65)	STEERING WHEEL	-	(28)	
(66)	STEERING WHEEL COLUMN			KICKPANEL
(59)	TRANSMISSION LEVER ON COLUMN			···-··
			Roof	
(03)	HARDWARE ITEM (SPECIFIC AREA UNKNOWN)		(25)	ROOF OR CONVERTIBLE TOP
(82)	INSTRUMENT(S)		(10)	
(83)	CONTROL KNOB(S) & LEVER(S) (FRONT)		(26)	, ,
(84)	PARKING BRAKE HANDLE IN FRONT		(24)	COAT HOOK
(67)	IGNITION KEY		(18)	
(06)	MIRROR		(39)	
(04)	HEATER OR AIR CONDITIONING DUCTS		(68)	ROOF MOUNTED CONTROLS/CONSOLE
(01)	AIR CONDITIONING OR VENTILATION OUTLET(S)		(69)	ROLL BAR
(80)	RADIO (BUILT IN)		` '	
(58)	ADD-ON TAPE DECK, RADIO, A/C		EXTERIO	OR SURFACE OF CASE VEHICLE
(68)	ROOF MOUNTED CONTROLS/CONSOLES		(37)	OUTSIDE SURFACE OF CASE VEHICLE
_			` •	(SPECIFIC AREA UNKNOWN)
REAR			(35)	HOOD OF CASE VEHICLE
(88)	SURFACE OF REAR INTERIOR		(60)	EXTERIOR OF CASE VEHICLE (E.G.
(23)	REAR WINDOW		` '	OUTSIDE MIRRORS, ANTENNA, TRIM)
	REAR WINDOW HEADER		(62)	EXTERIOR SIDE ROOF RAIL OF CASE VEHICLE
(50)	REAR SEAT CUSHION & BACK		(63)	TRUNK LID OF CASE VEHICLE
	_		(64)	TIRES OF CASE VEHICLE
	R-GENERAL			
	TRANSMISSION SELECTION LEVER (LOCATION UNK.)		BEYOND	CASE VEHICLE BOUNDARY
(59)	TRANSMISSION LEVER ON STEERING COLUMN			AREA EXTERIOR TO CAR (SPECIFIC AREA UNK.)
(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE		(70)	HOOD OF OTHER VEHICLE
	PARKING BRAKE HANDLE (LOCATION UNKNOWN)		(71)	OTHER VEHICLE EXTERIOR HARDWARE (E.G.
(84)	PARKING BRAKE HANDLE IN FRONT			OUTSIDE MIRRORS, ANTENNA, TRIM)
(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE		(73)	EXTERIOR SIDE ROOF RAIL OF OTHER VEHICLE
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)		(74)	HEADLIGHT OR FRONT GRILL OF OTHER VEH.
			(75)	TRUNK OF OTHER VEHICLE
(29)	FRONT SEAT-BACK(S)		(76)	OUTSIDE SURFACE OF OTHER VEHICLE
(51)			(77)	TIRES OF OTHER VEHICLE
(50)	REAR SEAT CUSHION & BACK		(78)	GROUND
(49)	ARMREST ON SEAT		(79)	WATER
(89)	UNDER SEAT BOTTOM		(80)	EXTERIOR OBJECT (NOT VEHICLE, GROUND,
				OR WATER. PLEASE DESCRIBE.)
(33)	RESTRAINT SYSTEM HARDWARE			
	RESTRAINT SYSTEM WEBBING		PENETRA	ATING OBJECTS
(87)	AIR CUSHION SKIN (AIRBAG)		(61)	OTHER VEHICLE
	AIRBAG (ACRS) COMPARTMENT DOOR/COVER		(72)	OBJECTS (DESCRIBE)
(46)	AIRBAG GAS			
(48)	KNEE RESTRAINT		MISCELL	
(30)				NO CONTACT (INVALID FIELD FORM CODE)
(42)		•		OTHER (E.G. FIRE. DESCRIBE)
	CHILD SEAT			SPARE TIRE
	INTERIOR LOOSE OBJECT			INDUCED
	OTHER OCCUPANT(S)			EJECTED, UNKNOWN CONTACT
	INTERNAL FLYING GLASS (FROM ANY SOURCE)		(98)	IMPACT FORCE, "WHIPLASH",
(41)	UNKNOWN INTERIOR SURFACE			HYPEREXTENSION/COMPRESSION
			(99)	UNKNOWN AREA OF CONTACT



INJURY CLASSIFICATION IC-4

CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)

1	BODY REGION

- (H) HEAD/SKULL
- (F) FACE
- (N) NECK
- (S) SHOULDER
- (X) UPPER EXTREMITIES
- (A) ARM (UPPER)
- (E) ELBOW
- (R) FOREARM
- (W) WRIST/HAND
- (C) CHEST
- (M) ABDOMEN
- (B) BACK
- (P) PELVIC/HIP
- (Y) LOWER EXTREMITIES
- (T) THIGH
- (K) KNEE
- (L) LEG (LOWER)
- (Q) ANKLE/FOOT
- (O) WHOLE BODY
- (U) UNKNOWN

3 LESION

- (L) LACERATION
- (C) CONTUSION
- (A) ABRASION
- (F) FRACTURE
- (P) PERFORATION, PUNCTURE
- (K) CONCUSSION
- (V) AVULSION
- (R) RUPTURE
- (S) SPRAIN
- (D) DISLOCATION
- (N) CRUSH
- (M) AMPUTATION
- (B) BURN
- (G) DETACHMENT, SEPARATION
- (Z) FRACTURE AND DISLOCATION
- (T) STRAIN
- (E) TOTAL SEVERANCE, TRANSECTION
- (O) OTHER
- (U) UNKNOWN

4 SYSTEM/ORGAN

- (S) SKELETAL
- (V) VERTEBRAE
- (J) JOINTS
- (D) DIGESTIVE
- (L) LIVER
- (N) NERVOUS SYSTEM
- (B) BRAIN
- (C) SPINAL CORD
- (E) EARS
- (O) EYES
- (A) ARTERIES
- (H) HEART
- (Q) SPLEEN
- (G) UROGENITAL
- (K) KIDNEYS
- (R) RESPIRATORY
- (P) PULMONARY/LUNGS
- (M) MUSCLES
- (T) THYROID, OTHER ENDOCRINE GLAND
- (I) INTEGUMENTARY (SKIN)
- (W) ALL SYSTEMS IN REGION
- (U) UNKNOWN

2 ASPECT

- (R) RIGHT
- (L) LEFT
- (B) BILATERAL
- (C) CENTRAL
- (A) ANTERIOR/FRONT
- (P) POSTERIOR/BACK
- (S) SUPERIOR/UPPER
- (I) INFERIOR/LOWER
- (W) WHOLE REGION
- (U) UNKNOWN

SEVERITY OF SYSTEM/ORGAN 4 LESION OF ASPECT OF

5 SEVERITY (OR *AIS*, ABBREVIATED INJURY SCALE)

- (0) NONE
- (1) MINOR
- (2) MODERATE
- (3) SERIOUS
- (4) SEVERE
- (5) CRITICAL
- (6) MAXIMUM
- (9) UNKNOWN



PN 3710-98 #1



-98 #











10-98 #7 Available

Best



Available













st Available



















st Available





98 #7









0-96 #











0-90





